Diagram 1


PANEL PATCH
MAINTENANCE
PLYWOOD OFFICE
ELECT. RM.
ELECTRICAL ROOM
6
5
4
3
2
1
8
7
ZONE
8
DRYER 1
DRYER 2
DRYER 3
DRYER 4
DRYER 5
DRY STACKER
Enlarged Area
North
SAW
MAKE-UP
020001